

VOWAIR: **UNIMAR** LINE: **AIEVIS. OMA**  
 Gate In  Gate Out  Pallet   
 TARE: **4420** MAX WEIGHT: **30580**  
 CONDITION: EMPTY  FULL   
 CONTAINER DESCRIPTION:  OTHER  HT HARD TOP  HT HALF HEIGHT  P. PLATFORM  P. FLAT RACK

SEAL 3 (CUSTOM) SEAL 3 (CUENT) SEAL 2 (LINE) SEAL 4 (OTHERS) **OMA 194823 20168230**  
 PRECINTOS:  OTHER  HT HARD TOP  HT HALF HEIGHT  P. PLATFORM  P. FLAT RACK

**REPARACIONES Y RECONSTRUCCIONES LEYES CON MANCHAS NO TRANSFERIBLE**  
**REPARACIONES Y RECONSTRUCCIONES LEYES CON MANCHAS NO TRANSFERIBLE**  
**REPARACIONES Y RECONSTRUCCIONES LEYES CON MANCHAS NO TRANSFERIBLE**

MACHINERY INSPECTION (ONLY GATE IN)  
 1- CUT CU  
 2- HOLES HO  
 3- DEBRIS DR  
 4- BAKEN BR  
 5- MISSING MS  
 6- CORRODED CO  
 7- DENT DT  
 8- BENT BT  
 9- COILED CD  
 10- BOWED BW  
 11- MARKING LABEL ML  
 12- LOOSE LD

CLEAN  DIRTY  GOOD CONDITION  DAMAGED

PARTS	LOCATION	TYPE OF DAMAGE	COMPONENT AND REPAIR METHOD	SIZE OF REPAIR	QTY.	OBSERVATIONS
UNDERSTR						
LEFT						
FRONT						
RIGHT						
DOOR						
INNER						
ROOF						

**SIN PRESENCIA DE AGENTES ENTOMOLOGICOS**

BY UNIMAR: **Y. Tacto** N° TRUCK: **79N-927** THY-996.  
 SIGNATURE: *[Signature]* NAME: *[Signature]* DATE: **05-04-23**  
 RECEIVE: *[Signature]*

