

D. Identidad : 41663231  
Brevete : F41663231  
Chofer : JUAN CARLOS HUAMAN  
MATAMOROS

Carga : Contenedores  
Contendor : MSGU9105683

Bultos : 2000

Peso1 : 40870.0

Peso2 : 17900.0

Neto : 22970.0

Ingreso : 07/02/2026 15:28:49

Salida : 07/02/2026 15:44:28

Posición : 1C30

I. Carguio : 07/02/2026 15:34:25

T. Carguio : 07/02/2026 15:35:03

Mfto : 2026-72 - MSC PISA


DAM : 127-2026-40-010909-00-0-00

Preo. : 003PL041654 /  
FX40092848 / 173391 /  
853AJZZ

Trans. : 20517650871

  
**J. Carlos H. Matamoros**

F. Conductor : **DNI: 41663231**

1. Línea Naviera / Shipping Line <b>MEDITERRANEAN SHIPPING CO.</b>		EIR-MSGU9105683 Equipmet Interchange Receipt (EIR) <b>MSGU9105683</b> 07/02/2026 15:34 07/02/2026 15:35 Técnico / Technician: <b>JOSE ROGELIO VARGAS PENA</b>		 <b>Puerto de Paracas</b> TERMINAL PORTUARIO PARACAS S.A. Punta Pejerrey Nro S/N Ica Pisco Paracas	
2. Nave y Viaje / Vessel's name <b>MSC PISA VOYAGE:NX606R</b>		3. Puerto / Port <b>TERMINAL PORTUARIO GENERAL SAN MARTÍN - TPGSM</b>		4. Gate <b>IN</b>	

DATOS GENERALES/GENERAL DATA					
5. Contenedor / Container <b>MSGU9105683</b>		6. ISO / ISO <b>45R1</b>		7. Tipo / Kind <b>REEFER HIGH CUBE</b>	
8. Tara / Tare <b>4560.0</b>	9. Peso Neto Maximo / Maximum net <b>30440.0</b>		10. Peso Bruto Maximo / Maximum gross <b>35000.0</b>	11. Estado / State <b>ESTADO (LLENO / FULL)</b>	12. Resultado / OutCome <b>OPERATIVO LIMPIO</b>
13. Clasificación / Classification <b>A</b>	14. Mes/Año Fabricación / Month/Year <b>11/2025</b>		15. Condición / Condition <b>FCL</b>	16. Precintos / Precints <b>003PL041654 / FX40092848 / 173391 / 853AJZZ</b>	

DATOS BOOKING / BOOKING DATA					
17. Reserva / Booking <b>EBKG15735134</b>		18. Cliente / Client <b>MEDITERRANEAN SHIPPING CO.</b>		19. Placa / Licence Plate <b>T3F828</b>	
20. Apellidos y Nombres / Full Name <b>F41663231 - JUAN CARLOS HUAMAN MATAMOROS</b>			21. Mercadería / <b>GRAPES</b>		
22. Humedad / Humidity <b>-</b>		23. Ventilación / Ventilation <b>-</b>		24. Tecnología / Technology <b>COT (Cold Treatment)</b>	
25. Temperatura Booking / <b>-0.5</b>			26. Temperatura Ajuste / Temperature Adjustment <b>-</b>		
27. Temperatura Carga / Temperature Load <b>-</b>			28. O2 / O2 <b>-</b>	29. CO2 / CO2 <b>-</b>	

REFRIGERADO / REEFER	
Door	Front
	Left Side
	Right Side
Top(Roof)	Inner
	Understructure

OBSERVACIONES / OBSERVATIONS

07/02/2026 15:35  
RECEIVE / DISPATCHERS  
**JOSE ROGELIO VARGAS PENA**

CONFORMITY RECEIPT  
**J. Carlos Matamoros**  
DNI 41663231

Location	Damage Type Description	Component Description	Repair Method Description	Responsible Description	Quantity	EIR Inspection EIR Nbr	Length(cm)	Width(cm)	Area(cm2)
-	-	-	-	-	-	EIR202600048685	-	-	-