


Placa : T3F828
Carreta : C5R980
D. Identidad : 41663231
Breveta : F41663231
Chofer : JUAN CARLOS HUAMAN
MATAMOROS

Carga : Contenedores
Contendor : SZLU9364670
Bultos : 1700
Peso1 : 37630.0
Peso2 : 18010.0
Neto : 19620.0
Ingreso : 05/02/2026 14:49:00
Salida : 05/02/2026 15:11:43
Posición : 1E14
I. Carguio : 05/02/2026 14:56:11
T. Carguio : 05/02/2026 14:57:05
Mfto : 2026-72 - MSC PISA
DAM : 127-2026-40-010366-00-0-00

Prec. : 003PL041679 /
FX40093040 / 173281

Trans. : 20517650871


J. Carlos H. Matamoros
DNI: 41663231

F. Conductor :

EIR-SZLU9364670

Shipmet Interchange Receipt (EIR)

SZLU9364670

05/02/2026 14:56

05/02/2026 14:57

JOSE ROGELIO VARGAS PENA



TERMINAL PORTUARIO PARACAS S.A.
Punta Pejerrey Nro S/N Ica Pisco Paracas

4. Gate
IN

TERMINAL PORTUARIO GENERAL SAN MARTIN - TPGSM

MEDITERRANEAN SHIPPING CO.

Inicio / Start:

Termino / Finished:

Técnico / Technician:

3. Puerto / Port

2. Nave y Viaje / Vessel's name

MSC PISA VOYAGE:NX606R

DATOS GENERALES/GENERAL DATA

5. Contenedor / Container

SZLU9364670

6. ISO / ISO

45R1

7. Tipo / Kind

REEFER HIGH CUBE

8. Tara / Tare

4660.0

9. Peso Neto Maximo / Maximum net

30340.0

10. Peso Bruto Maximo / Maximum gross

35000.0

11. Estado / State

ESTADO (LLENO / FULL)

12. Resultado / OutCome

OPERATIVO LIMPIO

13. Clasificacion / Classification

A

14. Mes/Año Fabricación / Month/Year Manufacturing

02/2026

15. Condicion / Condition

FCL

16. Precintos / Precints

003PL041679 / FX40093040 / 173281 /

DATOS BOOKING / BOOKING DATA

17. Reserva / Booking

EBKG15736058

18. Cliente / Client

MEDITERRANEAN SHIPPING CO.

19. Placa / Licence Plate

T3F828

20. Apellidos y Nombres / Full Name

F41663231 - JUAN CARLOS HUAMAN MATAMOROS

21. Mercaderia /

GRAPES

REFRIGERADO / REEFER

22. Humedad / Humidity

23. Ventilacion / Ventilation

24. Tecnologia / Technology

COT (Cold Treatment)

25. Temperatura Booking /

-0.5

26. Temperatura Ajuste / Temperature Adjustment

27. Temperatura Carga / Temperature Load

28. O2 / O2

29. CO2 / CO2

Door	Front	Left Side	Right Side
Top(Roof)	Inner	Understructure	

OBSERVACIONES / OBSERVATIONS

05/02/2026 14:57

RECEIVE / DISPATCHERS

JOSE ROGELIO VARGAS PENA

CONFORMITY RECEIPT

J. Carlos H. Matamoros
DNI: 41663231

Location	Damage Type Description	Component Description	Repair Method Description	Responsible Description	Quantity	EIR Inspection EIR Nbr	Length(cm)	Width(cm)	Area(cm2)
-	-	-	-	-	-	EIR202600048183	-	-	-